

SERVICE BULLETIN



No. : OIVL20050030

Date : 2005-08-30

Model	Factory	Factory Model	Suffix	Model No.	Factory	Factory Model	Suffix	Model No.
	EKHQ	KU-17LZ21	AAPZKZ	L17W36DVD	EKHQ	KU-17LZ23	AAPLKZ	KU-17WDVD
Buyer	Buyer Name	Buyer Code	Buyer Name	Buyer Code	Buyer Name	Buyer Code		
	LGEUS	US000001	LGEAI	US000002	ZENITH	US007515		
EFFECTIVE DATE	2005-08-29		EFFECTIVE FROM(SERIAL NO.)		2005-08-30			
Subject	KU-17LZ21 Micom Change Guide							
No.	Loc No.	Before Change		After Change		Note	K-Code	Remark
		Part No	DESC./SPEC.	Part No	DESC./SPEC.			

Reason Of Change

Problem : At maximum volume selection DVD audio level is low but other modes ok.
 Solution : Compared the audio level of DVD mode with other modes and now all modes
 Audio level at maximum volume is same. So firmware updated and Micom is changed.

If Earlier Version is less than 3.10 then use firmware version V0.01 else V3.14. For detailed description how to change and check the version refer to the Power Point file attached (KU-17LZ21_Micom_Change_Guide.ppt).

NOTE: Please check the H-DELAY and CSM data as explained in the file for fine adjustments (only for version V3.14).

[KU-17LZ21_Micom_Change_Guide.pdf](#)

** FILE THIS SERVICE BULLETIN WITH YOUR SERVICE MANUAL

NOTE(**) : INTERCHANGEABILITY CODE			KEY-WORD CODE
	Parts Set		
A	Original Early New Late	Original or new parts may be used in early or late production sets. Use original parts until exhausted, then stock new parts.	1. To improve performance 2. To improve productivity
B	Original Early New Late	Original parts may be used in early production sets only. New parts may be used in early or late production sets. Use original parts where possible, then stock new parts.	3. To improve reliability 4. Change of material or dimension
C	Original Early New Late	New parts only may be used in early or late production sets. Stock new parts.	5. Addition 6. Deletion
D	Original Early New Late	Original parts only may be used in early production sets. New parts may be used in late production sets only. Stock original and new parts.	7. Correction

CHIEF ENGINEER ,
Factory.

approved